

Date 08.02.99	Ref. No. <b>TV00899</b>	Model <b>KV-21C5D, KV-21X5D, KV-25C5D, KV-25K5D, KV-25R2D, KV-25X5D, KV-29C5D, KV-29K5D, KV-29X5D</b>	PC
Subject <b>Stereo/Mono Switching Noise</b>			IRIS 2544

## SYMPTOM

Audible stereo/mono switching noise in the Zweiton mode.

## CAUSE

Software error.

## SOLUTION

Replace IC001 on the A Board as listed below.

<i>Former</i>		<i>New</i>	
SAA5497PS-M1A-202	8-759-560-67	SAA5497PS-M1A-234 or later	8-759-584-74