SONY

Technical Bulletin

Date	Ref. No.	Model	PC
26.02.99	TV02399	KV-32WF1A, KV-32WF1B, KV-32WF1D, KV-32WF1E, KV-32WF1K, KV-32WF1U, KV-32WS2B, KV-32WS2D, KV-32WS2U	
Subject			IRIS
Part number info: FBT			1111

SYMPTOM

In these models, two types of FBT are being used which are not mechanically compatible.

SOLUTION

Use the correct FBT depending on the part number written on the FBT label.

Part number on FBT label	Service part number required	
8-598-816-00	1-453-257-11	
8-598-823-00	1-453-269-11	



